A Pulse Line Replacement RevX

SD-1003

Evolution Aircraft, Inc February 19, 2025

Status: Mandatory

Background:

It is possible for the pulse line that powers the mechanical fuel pump to fail within 5 years. Therefore this line is being changed to Aeroquip fuel line and should be checked annually and replaced at 5 years or on condition.

Scope:

The following serial numbers of the RevX weight-shift-control aircraft are affected by this safety directive: X001 - X0056.

Authorized Persons:

An owner/builder with a minimum of a sports pilot license is allowed to execute this safety directive in accordance with the instructions in this directive.

Tools and Articles Required:

10mm wrench 3/8" metric socket set Flat head screwdriver Oetiker crimper

Kits supplied by Evolution Aircraft, Inc Includes:


(1) Fuel line(2) Oetiker clamps

Compliance:

Compliance is mandatory 2 years after pulse line since new.

This is how to comply with this directive:

- Remove airbox
- Remove right side carburetor
- Remove airbox bracket
- Remove Adel clamp that holds rotary valve to engine case
- Remove Oetiker clamps on both ends of line
- Replace line
- Install new Oetiker clamps
- Reassemble



Testing:

• Start engine without using electric fuel pump and verify it runs for at least 5 minutes.

Logbook Entry:

Aircraft logbook should be marked with the following entry and dated and signed with mechanic's or pilot owner/builder's license number (if applicable):

"Safety directive SD-1003 from the manufacturer satisfied as per instructions."