

**Evolution Aircraft, Inc.
39440 South Ave.
Zephyrhills, Fl. 33542**

Safety Directive

**Data plate missing
date of manufacture**

SD-1018 RELEASED June 22, 2016

**Status:
Mandatory**

BACKGROUND:

It has been discovered that the date of manufacture is missing on the data plate of all REVO aircraft up until January 2016.

SCOPE:

The following serial numbers of REVO weight-shift-control that are affected by this Safety Directive: !001-1016 All serial numbers and serial number from 000550 -000617

AUTHORIZED PERSONS:

Owner with at least a Sport Pilot Rating

Type of Maintenance:

Line maintenance

TOOLS:

Drill

1/8" drill bit

Pop Rivet gun

Compliance

Compliance is mandatory and must be completed on or before the next annual inspection.

How to comply with this directive:

- 1) Remove the data plate by drilling out the 2 rivets using the 1/8th drill bit that hold it in place.
- 2) Send the data plate in to the factory for replacement: Evolution Aircraft Inc. 39440 South Av. Zephyrhills, Fl. 33542
- 3) Install the new data plate using the supplied rivets and pop rivet gun

Testing:

Make sure that rivets are secured and data plate cannot come loose

LOGBOOK ENTRY:

Aircraft logbook should be marked with the following entry and dated and signed "Safety Directive 1018 from the manufacturer satisfied as per instructions. Compliance with ASTM standards maintained."